

VARCHU MARC LLP

Material and reliability testing center

Shop No: 6&7, Ground floor, SMR Vinay Capitol, Hyderabad, Telangana, India. 500 042.

TEST REPORT

Issued to:

Kolor Canvas,
Hyderabad, Telangana.

Test Report No : VML/R/24-25/0158-1
Test Report Date : 23.01.2025

SAMPLE PARTICULARS

Page 1 of 1

Sample Details	: Kolor Canvas - Lime Wash Texture Paint
Sample Description	: Kolor Canvas - Lime Wash Texture Paint
Quantity	: 1 No's
Packing Details	: Good
Test Required	: Lead Content

Reference Number	: NA
Reference Date	: NA
Date of Receipt	: 21.01.2025
Date of Testing	: 21.01.2025
Date of Completion	: 23.01.2025
Location of Performed	: In house

TEST RESULTS

Sl. No.	Test Parameters	Unit	Results
1	Lead Content	ppm	<1

Method of Test: VML/MECH/SOP/01.

Disclaimer-1: This report relates only to the particular sample submitted for test.

Disclaimer-2: Sampling is done by customer.

END OF THE REPORT

REVIEWED & AUTHORIZED BY